Arran Court Water Main Break

Recently, a four-inch ductile iron pipe installed in 1987 broke on Arran Court. This pipe was incorrectly installed, and is also the wrong class of pipe (wall thickness) commonly used for non-pressure collection. This break was fixed by West Linn Water crews.



• Public Works

Source URL (retrieved on 2011-11-24 03:39):

http://westlinnoregon.gov/publicworks/arran-court-water-main-break